Approved For Release 2003/03/28 : CIA-RDP78T05161A001300010017-7 MAGERY ALYSIS TAFF PHOTOGRAPHIC INTELLIGENCE REPORT IRKUTSK AIRFRAME PLANT 25X IRKUTSK, USSR, **DECLASS REVIEW by NIMA/DOD** 25X1 CIA/PIR -75094 25X1 **MARCH** 1967 DATE COPY 110 GROUP 1
Excluded from automotic swngrading and declassification Approved For Release 2003/03/28 : CIA-RDP78T05161A001300010017-7




FIGURE 1. LOCATION MAP.

25X1

25X1

25X1

Approved For Release 2003/03/28/: PHA-RDP78 05161A001300010017-

CIA/PIR-75094

25X1

25X

some small storage/support buildings and an addition to the subassembly section (item 21).

Photographic coverage revealed that the addition to the subassembly section was under construction in a major portion of this addition was complete; the remaining portion was complete by

An area immediately east of the plant complex (containing items 9, 18, and 19) may be considered to be part of the plant. Items 18 and 19 are possible administration/engineering areas because of their proximity to the main entrance of the plant. Item 9 appears to be a possible motor pool/workshop and storage area with direct access to the main plant area (Figure 5). These buildings were not included in the total figures because they are outside the boundaries of the main plant area.

The current floorspace of the plant is

This figure also includes the multistoried administration/engineering floorspace. The current figures appear to be more accurate than those previously reported due to the better quality of stereo photography now available.

Irkutsk Airfield Northwest serves the plant as a test and flyaway field. It has a serviceable northwest/southeast concrete runway which measures approximately 8,260 by 230 feet. The runway is served by concrete parking aprons and taxiways. The parking aprons and taxiways cover an area of approximately 1,128,525 square feet.

Aircraft observed at the airfield and plant on included 17 probable FIREBAR/BREWER, 1 CAB, and 3 light straight wing.



25X1 25X1




FIGURE 4. IRKUTSK AIRFRAME PLANT NO 39,

25X1 FIGURE 3. IRKUTSK AIRFRAME PLANT NO 39

25X1 25X1

25X1 25X1

25X1

Approved For Release 20000 \$/200 RETA-RDP78 05161A0013000 10017-7

CIA/PIR-75094

25X1





FIGURE 5. LAYOUT OF IRKUTSK AIRFRAME PLANT NO 39.


- 5 -


25X1	Approved For Release 2062/03/28 PCTA RDP78T05161A001300010017-7 25X1 CIA/PIR-75094	25X1
	REFERENCES	
		25X1)
	MAPS OR CHARTS ACIC series, scale 1:200,000 DOCUMENTS	J 5X1
25X1	1. CIA. PIR-65134, Airframe Plant No 39, Irkutsk, USSR, May 66 (TOP SECRET	5X1
	PROJECT 31260/67 (partial answer)	



DDI IMAGERY ANALYSIS STAFF

PIR 75088






-8-

DDI IMAGERY ANALYSIS STAFF

PIR 75088



DDI IMAGERY ANALYSIS STAFF

PIR 75088

25X1

25X1

ITEM OF INTEREST NO. 1: Hanoi/Dong Hoi Rail Line

NAME

: Tu My RR. Bridge

BE

: NA

COORDINATES

: 18 59N - 105 34E, WG611001


PHOTO REFERENCE

•

MAP REFERENCE

: JOG (A) 1501, NE 48-7

The probable 2-span, deck-beam Tu My Railroad Bridge has been rebuilt and is now serviceable. The by-pass bridge which was formerly under construction has been partially dismantled and is unserviceable.



-11-

Approved For Release 2003/03/28E-CRETROP78T05161A001300010017-7

PIR 75088

25X1

25X1

DDI IMAGERY ANALYSIS STAFF

ITEM OF INTEREST NO. 2: Hanoi/Dong Hoi Rail Line

NAME : By-pass Construction around Thien Linh Dong RR. Bridge

BE : NA

COORDINATES : 19 43N - 105 42E; XG739813

PHOTO REFERENCE :

MAP REFERENCE : JOG (A) 1501, NE 48-3

A combination by-pass route and storage spur is under construction at UTM XG739813. The two piers of the probable 3-span by-pass bridge have been completed, and some track has been laid on 1 of the alternate roadbeds of the by-pass route. The main bridge ______ and another by-pass bridge ______ remain serviceable.

TRACK


BY-PASS BRIDGE U/C

ALTERNATE ROUTES

TILES

-12-

PIR 75088 FIGURE 11



Approved For Release 2003/03 25 CR - RDP78T05161A001300010017-7

DDI IMAGERY ANALYSIS STAFF

PIR 75088

ITEM OF INTEREST NO. 1: Hanoi/Haiphong Rail Line

NAME

: Hai Duong RR. By-pass Bridge

BE

: NA

COORDINATES

: 20 56N - 106 21E, XJ413168

PHOTO REFERENCE

25X1


MAP REFERENCE


: JOG (A) 1501, NF 48-15

The Hai Duong Railroad By-pass Bridge remains incomplete. However, considerable activity is observed in the area. Two barges are located on each side of the channel tied up to the respective completed bridge segments (Figure 12). Construction materials are located on these barges. Camouflage has been added to the completed segments of the bridge giving the structure the appearance of a causeway. Unidentified construction material is located adjacent to the western abutment (Figure 13). Two previously mentioned large pontoon bridge sections with railroad track (Report No. 1) are still located at UTM XJ390180 (not illustrated) and may possibly be used to complete the bridge if and when the main bridge is rendered unserviceable.

DDI IMAGERY ANALYSIS STAFF

PIR 75088





-15-

Approved F	or Release 2003/03/ %€ (RF ATRDP78T05161A001300	
		25X1
	DDI IMAGERY ANALYSIS STAFF	PIR 75088

ITEM OF INTEREST NO. 2: Hanoi/Haiphong Rail Line

NAME

: Rails

BE

: NA

COORDINATES

: 20 59N - 105 58E, XJ017211

PHOTO REFERENCE


: |

25X1

MAP REFERENCE

: JOG (A) 1501, NF 48-11

Considerable quantities of rails (not all illustrated) were observed stacked adjacent to the railroad track in the vicinity of UTM XJ017211.



Approved For Release 2003/03/28C:RFA-RDP78T05161A001300010017-7

DDI IMAGERY ANALYSIS STAFF

PIR 75088

25X1

25X1

ITEM OF INTEREST NO. 3: Hanoi/Haiphong Rail Line

NAME

: Rolling stock

BE

: NA

COORDINATES

: 21 00N - 105 58E, XJ005225


PHOTO REFERENCE

: JOG (A) 1501, NF 48-11

MAP REFERENCE

Ten flat cars, each carrying 2 probable 7 metric ton POL tanks, were observed at UTM XJ005225 on the Hanoi/Haiphong Rail Line and may indicate either a shortage of conventional meter gauge POL tank cars on this line

or the transport of prefabricated tanks.




-18-

KEY

All Maps within this report have been keyed in the following manner:

- ☆ Main bridge bombed now serviceable.
- * By-pass bridge or bridges serviceable.
- Main bridge unserviceable.
- All bridge crossing facilities unserviceable.
- lacktriangle By-pass bridge under construction.
- Original bridge has not been damaged or destroyed based on available photography.
- x Extent of rail line covered by available, interpretable photography.
- ltem of interest. Turn to the item number within the section for further information.



Approved For Release 2003/65/29: SIA RDP78T05161A001300010017-7

25X